	Description	Points Deducted
Item N° 22	Dishwashing / equipment washing facilities designed, constructed, maintained,	0
	installed, located, operated, TMDs, test kits	
Location N°2	LE GRAND BLEU	
Violation	The wash temperature gauge on the ware wash machine was not easily readable due	e to condensation.
Corrective action	Instructed the crew to replace the wash temperature gauge (7.5.2.2.1)	
	, , , , , , , , , , , , , , , , , , , ,	
Item N°	Description	Points Deducted
28	Equipment / utensil / linen / single / service storage, handling, dispensed; clean frequency	2
Location N°4	MAIN GALLEY - POTWASH	
Violation	The storage shelf over the three-compartment sink was used to store clean pots and located over all three sinks and subject the clean items over the wash and rinse sink was noted on the last inspection	
Corrective action	Instructed the crew to leave the shelf over all three sinks free of clean pots and	utensils (7.5.7.3)
Item N°	Description	Points Deducted
33	Decks / Bulkheads / deck heads construction, repair, clean	0
	LE COLAND DUEL	
Location N°1	LE GRAND BLEU Unsealed pipe penetrations were behind the soft serve ice cream machine located or	n the port side buffet
Violation		1
Corrective action	Instructed the crew to seal the pipe penetrations (7.7.4)	
Item N°	Description	Points Deducted
Item N°	Description Decks / Bulkheads / deck heads construction, repair, clean	Points Deducted
33	Decks / Bulkheads / deck heads construction, repair, clean	
33 Location N°3	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE	
33 Location N°3 Violation	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE Loose profile strips were noted on the bulkhead portside service line	
33 Location N°3	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE	
33 Location N°3 Violation	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE Loose profile strips were noted on the bulkhead portside service line	Points Deducted 0
33 Location N°3 Violation	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE Loose profile strips were noted on the bulkhead portside service line Instructed the crew to fix the profile strips on the bulkhead (7.7.4.2.3) Description	0
33 Location N°3 Violation Corrective action	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE Loose profile strips were noted on the bulkhead portside service line Instructed the crew to fix the profile strips on the bulkhead (7.7.4.2.3)	0
33 Location N°3 Violation Corrective action	Decks / Bulkheads / deck heads construction, repair, clean MAIN GALLEY – SERVICE LINE Loose profile strips were noted on the bulkhead portside service line Instructed the crew to fix the profile strips on the bulkhead (7.7.4.2.3) Description	

	Instructed the crew to replace the cracked and broken tiles and to renew the grouting between the tiles (7.7.4.2.3)
--	---

MSV CLUB MED 2

SERVICES ET TRANSPORTS

Item N°	Description	Points Deducted
40	IPM procedures developed; followed; outer openings protected	0
Location N°6	INTEGRATED PEST MANAGEMENT	
Violation	Credentials / Certificates of training were not available for the instructor providing	training for the vessel
Corrective action	We are looking for to provide, through a specialized company, training to our the vessel in order to obtain a certificate of training (8.0)	instructors onboard

Item N°	Description	Points Deducted
41	Child Activity Center facilities, diaper changing, operation	0

Ī	Location N°5	VENTILATION
	Violation	The drain pans on the ventilation units were very corroded

Corrective action	Instructed the crew to clean the drain pans and replace those with too much corrosion (9.2.1.2)